

FIG. 1





Fig. 2(b)






FIG. 3




Fig. 4

\												
	X_1	X_2	X ₃	X_4	X_5	X_6	X ₇	X ₈	X ₉	X ₁₀	X ₁ .	1X12
Y ₁	TA	TA	T_A	TA	T_A	T _A	TA	TA	TA	TA	TA	TA
Y ₂	T_A	TA	T_A	T_A	TA	TA	TA	TA	T_A	T_A	TA	TA
Y ₃	T_A	TA	T_A		T_A	T_A				T_A	TA	TA
Y ₄	TA	TA	TA	T_{A}	TA	T_A				TA	TA	TA
Y_5	TA	TA	T_A			TA		TA		TA	TA	TA
Y ₆	TA											TA
Y ₇	T_A	T_{A}	TA	TA	_		TA					
Y ₈	TA	TA							TA			TA
Y_9	TA	TA	TA	T	1	TA	TA			TA	TA	TA
Y ₁₀	TA		TA	TA	TA	TA				TA	TA	TA
Y ₁₁	TA											TA
Y ₁₂	TA	TA	TA		1		TA	TA	TA	TA	TA	TA

Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




FIG. 10